



Art of speed
210 Rope Mill Parkway
Woodstock, GA 30188
(404) 757-0952
keith@artofspeed.com

Invoice for RO #65

Service Advisor: Keith Wilson

Posted Date: 12/17/25 at 12:45 PM EST

Client: [REDACTED]

Vehicle: 1974 International Scout II Base

[REDACTED] [REDACTED]	1974 International Scout II Base 5.6L 8Cyl GAS V345 Naturally Aspirated VIN: N/A License: N/A Color: White Odometer In: 11922 / Out: 11923	RO # 65 Time-In: 10/21/25 at 09:24 AM EDT Save Parts: No
--------------------------	---	--

1 - Power steering

Tech: K Wilson

Note: Replaced pressure hose and return line hose. all new ATF power steering fluid.

Labor:		1.50 hrs	\$120.00	\$180.00
Parts:	Carquest FDO PS Pressure	1	\$39.99	\$39.99
	PS hose PS hose	1	\$4.39	\$4.39

✓ Approved on 11/11/25 at 10:55 AM EST

Subtotal \$224.38 + est. Tax \$2.66

\$227.04

2 - Parking Brake

Tech: K Wilson

Note: installed new brake shoes, Adjusted rear parking brake.

Labor:		2.00 hrs	\$120.00	\$240.00
--------	--	----------	----------	----------

✓ Approved on 11/11/25 at 10:55 AM EST

\$240.00

3 - Radiator Flush

Tech: K Wilson

Note: Tapped the threads on over flow for radiator that was leaking.

Labor:		1.50 hrs	\$120.00	\$180.00
Part:	Fram Antifreeze	5	\$15.94	\$79.70

✓ Approved on 11/11/25 at 10:55 AM EST

Subtotal \$259.70 + est. Tax \$4.78

\$264.48

4 - Transmission oil change

Tech: K Wilson

Labor:		1.50 hrs	\$120.00	\$180.00
Parts:	Fram Transmission Fluid	6	\$12.31	\$73.86
	Carquest Trans Filter	1	\$17.82	\$17.82
	Victor Reinz Trans Gasket	1	\$15.11	\$15.11

✓ Approved on 11/11/25 at 10:55 AM EST

Subtotal \$286.79 + est. Tax \$6.41

\$293.20

5 - Battery

Note: Added one bolt to battery tray to tighten down. Battery has 3 year warranty.

Part:	DieHard Gold Battery	1	\$275.99	\$275.99
-------	----------------------	---	----------	----------

✓ Approved on 11/11/25 at 10:55 AM EST

Subtotal \$275.99 + est. Tax \$16.56

\$292.55

6 - Oil Change

Tech: K Wilson

Note: Tightened up all oil pan bolts and put RTV on 2 bolts that were leaking. Tightened Valve cover bolts. Removed dust cover for bell housing and cleaned and put 4 new bolts back on bell housing dust cover.

Labor:		1.30 hrs	\$120.00	\$156.00
Parts:	Valvoline 20w50-Racing oil with zinc	8	\$12.99	\$103.92
	Mobil Oil Filter	1	\$27.99	\$27.99

✓ Approved on 11/11/25 at 10:55 AM EST

Subtotal \$287.91 + est. Tax \$7.91

\$295.82**7 - Brakes**

Tech: K Wilson

Note: Bled brake fluid and cleaned out brake reservoir. Installed front brake pads. Cleaned up front locking hubs.

Labor:		4.00 hrs	\$120.00	\$480.00
Parts:	Wearever Brake Shoe	1	\$58.99	\$58.99
	IH Front pads	1	\$105.09	\$105.09

✓ Approved on 11/11/25 at 10:55 AM EST

Subtotal \$644.08 + est. Tax \$9.84

\$653.92**8 - Pressure washed under Vehicle**

Tech: K Wilson

Note: Wire brushed front and rear diff and transfer case. Tightened transfer case bolts.

Labor:		1.50 hrs	\$120.00	\$180.00
--------	--	----------	----------	----------

✓ Approved on 11/11/25 at 10:55 AM EST

\$180.00**9 - Tires flipped around**

Note: Pep boys flipped around so the raised white letter are facing out.

Part:	Pep Boys Flip tires around	1	\$81.04	\$81.04
-------	----------------------------	---	---------	---------

✓ Approved on 11/11/25 at 10:55 AM EST

Subtotal \$81.04 + est. Tax \$4.86

\$85.90**10 - Wiring ignition switch**

Tech: K Wilson

Note: Right rear brake bulb replaced, disconnected push button switch to be able to start vehicle.

Labor:		1.20 hrs	\$120.00	\$144.00
--------	--	----------	----------	----------

✓ Approved on 11/11/25 at 10:55 AM EST

\$144.00**11 - Miscellaneous**

Tech: K Wilson

Note: Fixed parking brake pull handle. .5hr I had to cut down a bolt and paint it black to sit flush on passenger head. .5hr

Labor:		1.00 hrs	\$120.00	\$120.00
--------	--	----------	----------	----------

✓ Approved on 11/11/25 at 10:55 AM EST

\$120.00**12 - Panting rear skid plate**

Tech: K Wilson

Note: Sanded down skid plate and tow hitch and panted black.

Labor:		3.00 hrs	\$120.00	\$360.00
Part:	All Purpose Gloss black	2	\$3.78	\$7.56

✓ Approved on 11/11/25 at 10:55 AM EST

Subtotal \$367.56 + est. Tax \$0.45

\$368.01

13 - Shocks Tech: K Wilson Note: Replaced all 4 Shocks. I used CV Joint Straps instead of zip ties. Loos and hold much better.				
Labor:	Shock Replacement	1.50 hrs	\$120.00	\$180.00
Part:	Rancho Shock Absorbers	1	\$461.52	\$461.52
✓ Approved on 11/11/25 at 10:55 AM EST				\$641.52

14 - Wire loom Note: Covered up wires in the engine bay as best as i could. 1hr no charge				
✓ Approved on 11/11/25 at 10:55 AM EST				0

15 - A/C line through fire wall Tech: K Wilson Note: Made a plate to cover A/C line holes through fire wall and panted black				
Labor:		1.00 hrs	\$120.00	\$120.00
✓ Approved on 11/11/25 at 10:55 AM EST				\$120.00

16 - Horn Tech: K Wilson Note: Took apart steering wheel to find out why horn was not working. Found the wire came loose and found steering nut was loose. I put blue LOCK TIGHT on nut and torqued nut back down and made the wire much tighter to not come off again.				
Labor:		1.00 hrs	\$120.00	\$120.00
✓ Approved on 11/11/25 at 10:55 AM EST				\$120.00

17 - Brake Booster Tech: K Wilson Note: Bleed Brakes, reset rear brake shoes				
Labor:	Install Brake Booster	4.00 hrs	\$120.00	\$480.00
Parts:	DNC Brake Booster	1	\$608.99	\$608.99
	Shipping Shipping	1	\$55.00	\$55.00
✓ Approved on 12/17/25 at 12:33 PM EST				Subtotal \$1,143.99 + est. Tax \$39.84 \$1,183.83

18 - Front Diff gasket Tech: K Wilson Note: Pulled off cover that was leaking and found there was no gasket just a bunch of RTV. Sanded diff cover and painted black. Put new gasket and new oil.				
Labor:		2.00 hrs	\$120.00	\$240.00
Parts:	Fel-Pro Gasket	1	\$11.19	\$11.19
	Fram 80w90	2	\$13.99	\$27.98
✓ Approved on 12/17/25 at 12:33 PM EST				Subtotal \$279.17 + est. Tax \$2.35 \$281.52

19 - Rear Diff Tech: K Wilson Note: Pulled cover off. Painted cover and reinstalled.				
Labor:		2.00 hrs	\$120.00	\$240.00
Parts:	Fram 80w90	3	\$13.99	\$41.97
	Fel-Pro Diff Cover Gasket	1	\$10.79	\$10.79
✓ Approved on 12/17/25 at 12:33 PM EST				Subtotal \$292.76 + est. Tax \$3.17 \$295.93

20 - Panting Frame

Tech: K Wilson

Note: Wire brushed the best that we could all the dirt and grease from the frame. Taped and masked around the frame and painted side and bottom of frame. We painted the front and rear axle.

Labor:		8.00 hrs	\$120.00	\$960.00
Part:	Rust-Oleum Pro Blk Top Undercoat	6	\$17.82	\$106.92

✓ Approved on 12/17/25 at 12:33 PM EST

Subtotal \$1,066.92 + est. Tax \$6.42

\$1,073.34

21 - Frame Welding

Tech: K Wilson

Note: Drove car over to Car 1 They cut out old rusted part and and welded a new piece in and painted it.

Labor:	3.00 hrs	\$100.00	\$300.00
---------------	----------	----------	----------

✓ Approved on 12/17/25 at 12:33 PM EST

\$300.00

22 - Parts

Parts:	Audio Line 30A Circuit Breaker	1	\$17.99	\$17.99
	Rheedal 4.25 Center Caps Push Through	1	\$54.99	\$54.99

✓ Approved on 12/17/25 at 12:33 PM EST

Subtotal \$72.98 + est. Tax \$4.38

\$77.36

23 - Door Adjustment

Note: Adjusted door Alignment to let door close easier

✓ Approved on 12/17/25 at 12:33 PM EST

0

0

RO Fees

Fee:	Shop supplies	\$133.56
------	---------------	----------

<i>Subtotal</i>	\$133.56
-----------------	-----------------

Work Authorization Signature:

Total Labor: \$4,860.00

Total Parts: \$2,288.79

Total Fees: \$133.56

Subtotal: \$7,282.35

Taxes: \$117.65

Grand Total: \$7,400.00

BALANCE DUE: \$0.00

X

✓ PAID

Payment History

Payment Signature

12/17/25	[REDACTED]	\$7,400.00	Check Payment
----------	------------	------------	------------------