

The Scoutman  
2475 Jason Industrial Pkwy  
Winston, GA 30187  
beverly@thescoutman.com  
www.thescoutman.com



**BILL TO**

[REDACTED]  
[REDACTED]  
[REDACTED]

**INVOICE 1272**

**DATE** 08/06/2019 **TERMS** Due on receipt

**DUE DATE** 08/29/2019

| DESCRIPTION                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | QTY  | RATE   | AMOUNT |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|--------|--------|
| <b>Services</b><br>Requests:<br>Assess motor and advise if anything needs attention - has leaks but nothing drastic.<br>Battery is being drained even after replacement- assess alternator and determine root cause of drain.<br>Horn inoperable - [REDACTED] purchased a GT steering wheel with horn to install.<br>Assess fuel gauge and temp gauge functionality.<br>Assess wiring as stereo fades in and out while in use even after head unit replaced, determine if wired correctly as it stays on after the engine is turned off.<br>Assess gauge indicator lights and make suggestions for increased brightness or replacement if necessary.<br>Visibility is poor at night with headlights - recommendation requested for bright but not too modern.<br>Evaluate fuel tank as it leaks from underneath after refueling.<br>Install Tuff Built locking console provided by [REDACTED] | 1    | 0.00   | 0.00   |
| <b>Upgraded Alternator</b><br>GM style one wire                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | 1    | 205.00 | 205.00 |
| <b>Alternator Belt</b><br>gates                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | 1    | 25.00  | 25.00  |
| <b>Labor</b><br>install new alternator and belt                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | 1.50 | 120.00 | 180.00 |
| <b>Horn</b><br>horn                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | 1    | 25.00  | 25.00  |
| <b>Labor</b><br>install new horn clean all connections                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | 5    | 120.00 | 600.00 |

| DESCRIPTION                                                                                                                                                                       | QTY | RATE     | AMOUNT   |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|----------|----------|
| install steering wheel<br>install new console<br>Clean up wiring /fuse block and gauge wiring<br>Re-wire radio<br>Clean fuse block and terminals<br>New negative battery terminal |     |          |          |
| <b>Parts</b><br>Fuel / Amp Meter                                                                                                                                                  | 1   | 150.00   | 150.00   |
| <b>Parts</b><br>Oil / Temp Gauge                                                                                                                                                  | 1   | 150.00   | 150.00   |
| <b>Labor</b><br>Install white decals on refurbished gauges                                                                                                                        | 1   | 120.00   | 120.00   |
| <b>Oil Pressure switch</b><br>For original gauge                                                                                                                                  | 1   | 40.00    | 40.00    |
| <b>Dash Light Socket</b><br>Scout II                                                                                                                                              | 2   | 4.00     | 8.00     |
| <b>Parts</b><br>Upgrade headlight bulb socket wiring                                                                                                                              | 1   | 20.00    | 20.00    |
| <b>Services</b><br>Additional Items below as of 8/12/19                                                                                                                           | 1   | 0.00     | 0.00     |
| <b>Parts</b><br>Tartan plaid fabric<br>Please allow 3 days for shipment and an additional week to upholster and install seats                                                     | 1   | 200.00   | 200.00   |
| <b>Parts</b><br>Marine grade vinyl matched to existing vinyl and dash pad                                                                                                         | 6   | 30.00    | 180.00   |
| <b>Re-upholster Seats</b><br>New upholstery. Bucket seats, rear bench, door panels and console top                                                                                | 1   | 1,800.00 | 1,800.00 |
| <b>Labor</b><br>Remove seats and panels - reinstall after upholstery work is completed                                                                                            | 4   | 120.00   | 480.00   |
| <b>Labor</b><br>Rewire speakers into door panels<br>Cut out holes for new 6.5 speakers in door ,in metal door panel and in new upholstered door panel insert                      | 4   | 120.00   | 480.00   |
| <b>Parts</b><br>Sound Dampener for interior of each door panel                                                                                                                    | 1   | 125.00   | 125.00   |
| <b>Labor</b><br>Install Sound Dampener                                                                                                                                            | 1   | 120.00   | 120.00   |
| <b>Services</b><br>Remove aftermarket gauge cluster, and tachometer. No charge.                                                                                                   | 1   | 0.00     | 0.00     |
| <b>Parts</b><br>Original wiper blade set                                                                                                                                          | 1   | 40.00    | 40.00    |
| <b>Oil Filter, V8 Wix</b>                                                                                                                                                         | 1   | 11.00    | 11.00    |
| <b>Rotella SAE 30, quart</b>                                                                                                                                                      | 7   | 8.50     | 59.50    |
| <b>Alternator Belt</b>                                                                                                                                                            | 1   | 25.00    | 25.00    |
| <b>Power Steering Belt</b>                                                                                                                                                        | 1   | 25.00    | 25.00    |

| DESCRIPTION                                                                                                                                                                                                                             | QTY  | RATE   | AMOUNT |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|--------|--------|
| Scout II                                                                                                                                                                                                                                |      |        |        |
| <b>Air Filter, Wix</b><br>Scout II                                                                                                                                                                                                      | 1    | 14.00  | 14.00  |
| <b>Spark Plugs IH V8</b>                                                                                                                                                                                                                | 1    | 26.00  | 26.00  |
| <b>Plug wires</b><br>MSD Streetfires, cut to fit 8mm                                                                                                                                                                                    | 1    | 100.00 | 100.00 |
| <b>Labor</b><br>Oil change, top off all fluids, replace alternator belts and power steering belt, air filter, spark plugs and wires                                                                                                     | 2.50 | 120.00 | 300.00 |
| <b>Aluminum 3 Core Radiator Scout II (deleted)</b><br>Scout II, Custom built radiator                                                                                                                                                   | 1    | 450.00 | 450.00 |
| <b>Parts</b><br>Replace coolant hoses and clamps                                                                                                                                                                                        | 1    | 100.00 | 100.00 |
| <b>Antifreeze</b>                                                                                                                                                                                                                       | 3    | 16.00  | 48.00  |
| <b>Services</b><br>Install coolant overflow tank supplied by █████, no charge                                                                                                                                                           | 1    | 0.00   | 0.00   |
| <b>Labor</b><br>Replace radiator and all associated hoses and clamps, refill coolant                                                                                                                                                    | 1.50 | 120.00 | 180.00 |
| <b>Ignition switch</b><br>New ignition switch                                                                                                                                                                                           | 1    | 38.00  | 38.00  |
| <b>Headlight Switch</b>                                                                                                                                                                                                                 | 1    | 40.00  | 40.00  |
| <b>Dimmer Switch, Scout II</b><br>Scout II                                                                                                                                                                                              | 1    | 30.00  | 30.00  |
| <b>Turn Signal Return Switch, Scout II</b><br>Scout II                                                                                                                                                                                  | 1    | 60.00  | 60.00  |
| <b>Labor</b><br>Installation of ignition switch                                                                                                                                                                                         | 1    | 120.00 | 120.00 |
| <b>Parts</b><br>Memphis 6.5 speakers                                                                                                                                                                                                    | 1    | 120.00 | 120.00 |
| <b>Notes</b><br>Dropped fuel tank and replaced fuel sender along with vent hose.<br>10/17/19: Brought back in to replace the fuel filler neck as it was missing the metal band on the inside which maintains its shape when clamped to. | 1    | 0.00   | 0.00   |

Ways to pay



View and pay

PAYMENT6,694.50

TOTAL DUE\$0.00